

# Summary of Faults Repaired by Software Upgrade

## GD-03 / TL-01 / AD-01 / DM-01 / FS-02

How to display the firmware version installed in the audio:

1. Press SETUP button.
2. Tap System and then Device Information on the audios' LCD panel.

Ref.	Audio Mode	Fault Description	Fault Repaired Firmware ID
1	General	Audio LCD illumination flickers at various dashboard illumination dimmer control settings.	SW Ver: 2.05.10 Micom: 3.28.00 Platform: 1.76.00
2	General	Audio does not operate but LCD backlight is illuminated.	
3	iPod	iPod Touch™ (30Pin) does not start play when first connect to the car USB socket or when key is switched to ACC.	
4	USB, iPod, My Music	RDM (random) function changes to RPT (repeat) function after the ACC is switched OFF and then ON.	
5	General	LHS knob does not display audio settings when pressed.	
6	General	Solves boot loader issue where audio unit may not operate after firmware update.	
7	CarPlay™	CarPlay feature addition. Improved hands-free external party listening clarity when using CarPlay™ for both wide and narrow-band connections.	
8	Bluetooth	Further improved hands-free external party listening clarity. In some cases, a call may not be ended by selecting the on-hook (red phone icon) button on the audio unit LCD. In some cases, Bluetooth disconnection and reconnection occurs at the commencement of a call.	
9	Tuner	Preset memories are lost when vehicle is started	
10	Reverse Camera	Camera image may display when vehicle is not in reverse gear or camera image may not appear or LCD may show green or black screen or a still image from the camera.	
11	Android Auto™	Android Auto™ feature addition	
12	LCD Display	Blank (black), green or noisy image may be displayed on the LCD screen when the vehicle is started and the transmission shifted to Drive	
13	Reverse Camera	Blank (black), green or noisy image may be displayed on the LCD screen after the transmission is shifted to reverse	
14	Reverse Camera	Reverse camera image may continue to be displayed on the LCD after transmission is shifted from reverse to another gear.	
15	Bluetooth	In some cases a call may not be ended when selecting the red 'hang-up' button on the audio unit LCD	
16	Bluetooth	Bluetooth disconnection and reconnection occurs at the commencement of a phone call	
17	Clock	Clock and date occasionally loses memory	
18	Apple CarPlay	Clicking/popping noise when playing audio through Apple CarPlay	
19	Apple CarPlay / Android Auto	Poor radio reception due to missng antenna amplifier power supply after CarPlay or Android Auto navigation instruction or phone message chime	